

GENERAL HAZARD & RISK ASSESSMENT

Department	Mill Wide	Date of assessment	26-Sep-2003
Operation	Working inside Guards	Reference No	649 Pabiac
Assessor(s)			

Standards	<ul style="list-style-type: none"> HS(G) 155 Slips and Trips 1996 ISBN 0 7176 1145 0 Management of Health and Safety at Work Regulations 1999 	<ul style="list-style-type: none"> PABIAC Application of the Provision and Use of Work Equipment Regulations to the paper and board industry - Published - 1996 - ISBN 0 7176 1287 2 PABIAC Making paper safely (Managing health and safety in the paper making process)- Published 2001 - ISBN 0 7176 1907 9
------------------	---	---

Task		Working inside Guarded areas					
Hazard	Potential harm	Existing control measures / control strategies	Remedial actions / control strategies	Person responsible	Due on	Done on	Risk Rating
Entanglement	<ul style="list-style-type: none"> Amputation Broken Limbs Crushing Cuts and bruises Cuts to hands and fingers Electrocution Loss of life Trapping 	Machine guards of sound construction and installed correctly and either bolted in position so that a hand tool is required to remove the guard or the guard is electronically interlocked.	Assuming that the task is essential and there is no other way to perform this, a written safe system of work in very careful and considered detail will be provided before work is carried out inside the guard	Responsible Person	26-Sep-2003		25
			Various appropriate provisions will be made inside the guard to still prevent exposure to dangerous parts	Responsible Person	26-Sep-2003		
		Controls are outside of the guards so that adjustments can be made from outside of the area	All persons will be trained to work to these safe systems of work prior to attempting such work	Responsible Person	26-Sep-2003		
		Use of video camera to see closer and can be played back for analysis	Only one person inside the guards where practicable	Responsible Person	26-Sep-2003		
			In for the shortest possible time	Responsible Person	26-Sep-2003		
		A written safe system of work					
		Sentry at the e stop at all times	Responsible Person	26-Sep-2003			